



P68 Variants

(Including Partenavia manufactured aircraft)

***Index of Service Bulletins, Service Letters
and Service Instructions
Issued on 01 March 2010***

NOR10.777-1

Service Bulletins

SB. No.	Rev. No.	SUBJECT	VARIANT AFFECTED	Rev. DATE	TYPE	TIME OF COMPLIANCE
01	1	CABIN FLOOR TRAP	INACTIVE Refer to Service Letter No. 15			
02		ENLARGED BAGGAGE DOOR	INACTIVE Refer to Service Letter No. 15			
03		APPLICATION OF CHECK VALVES TO THE FUEL TANK BREATHERS	P68	JAN 72	MANDATORY ACTION	WITHIN NEXT 100 FLIGHT HOUR S.B. RECEPTION
04		LIMIT STOP PILOT'S SEATS	P68	MAR 72	MANDATORY ACTION	ON RECEPTION OF THIS S.B.
05		ALTERNATE STATIC AIR VENT	P68	MAR 73	RECOMMENDED ACTION	ON CUSTOMER OPTION
06		PROPELLER PITCH CONTROL LEVERS	P68	JUL 73	MANDATORY ACTION	AT NEXT INSPECTION
07		SHIMMY DAMPER CONNECTION	P68	OCT 73	MANDATORY ACTION	AT NEXT INSPECTION
08		RETAINING STRAP ATTACHMENT POINTS IN BAGGAGE LOCKER	P68	DEC 73	INFORMATION ONLY	ON CUSTOMER OPTION
09		CHANGE IN THE POSITIONING OF ELECTRICAL SWITCHES AND VOLTAMMETER	P68	DEC 73	INFORMATION ONLY	ON CUSTOMER OPTION
10		FUNCTIONING OF ALTERNATOR WARNING LIGHT RELAY	P68, P68B	JUN 74	MANDATORY ACTION	WITHIN NEXT 50 FLIGHT HOUR
11		MODIFICATION OF FUEL TANK VENT	P68, P68B	OCT 74	RECOMMENDED ACTION	ON CUSTOMER OPTION
12		ELIMINATION OF LANDING LIGHT REFLECTIONS ONTO THE INSTRUMENT PANEL	P68, P68B	OCT 74	RECOMMENDED ACTION	ON CUSTOMER OPTION
13		INSTALLATION OF THE ATTACHMENT POINTS FOR SHOULDER HARNESS FOR THE TWO FRONT SEATS	P68B	OCT 74	INFORMATION ONLY	ON CUSTOMER OPTION
14	1	FUEL SELECTOR PLACARDS	P68, P68B	MAR 85	RECOMMENDED ACTION	ON CUSTOMER OPTION
15		PLAY IN THE STABILATOR/STABILATOR TORQUE TUBE ASSY	P68, P68B	MAR 75	MANDATORY ACTION	WITHIN THE NEXT 25 FLIGHT HOUR
16		SUBSTITUTION OF FLYING CONTROL WHEEL BEARING SUPPORT (SX & DX)	P68-P68B	APR 75	RECOMMENDED ACTION	ON RECEIPT OF MODIFICAT. KIT
17		INSTALLATION OF A HISONIC RFI 40 FILTER AND A 0.05 mFd CAPACITOR IN EACH ALTERNATOR LINE	P68, P68B	JUN 75	RECOMMENDED ACTION	ON CUSTOMER OPTION
18		INSTALLATION OF "STALL SPEED" PLACARDS AND "SPEED LIMITATIONS" PLACARD - UPDATED	P68B	JUN 75	MANDATORY ACTION	WITHIN THE NEXT 20 FLIGHT HOUR

Note (*): Periodical Inspection Bulletin

ISSUED

Service Bulletins

S.B. No.	Rev. No.	SUBJECT	VARIANT AFFECTED	Rev. DATE	TYPE	TIME OF COMPLIANCE
19		FUEL FILTER RH ENGINE	P68, P68B	JUN 75	MANDATORY ACTION	IMMEDIATELY
20		INSTALLATION OF "STALL SPEEDS" AND "SPEED LIMITATION" PLACARD – UPDATED	P68	JUL 75	MANDATORY ACTION	WITHIN THE NEXT 20 FLIGHT HOUR
21		INCREASE OF A/C MAX T.O. WEIGHT FROM 4100 LBS TO 4321 LBS	P68	JUL 75	INFORMATION ONLY	ON CUSTOMER OPTION
22		ENGINE MOUNT	P68, P68B	AUG 75	MANDATORY ACTION	SEE PART I AND PART II
23		ANTISHIMMY SUPPORT SUBSTITUTION	P68	OCT 75	MANDATORY ACTION	ON RECEIPT OF MODIFICAT. KIT
24		FITTING OF GOODYEAR 7.00-6 TYPE RIB 8 MAINWHEEL TYRES	P68, P68B	NOV 75	INFORMATION ONLY	ON CUSTOMER OPTION
25	1	ENGINE ALTERNATE AIR SYSTEM	P68	NOV 93	MANDATORY ACTION	WITHIN THE NEXT 50 FLIGHT HOUR
26		RETROFIT OF DIRECT VISION PORTHOLE TO RIGHT HAND WINDSHIELD	P68, P68B	APR 76	INFORMATION ONLY	ON CUSTOMER OPTION
27	A	INSTALLATION OF COMBUSTION HEATER	INACTIVE Refer to Service Letter No. 15			
28		IMPROVEMENT TO ENGINE EARTH INSTALLATION	P68, P68B	MAY 76	RECOMMENDED ACTION	ON RECEIPT OF EARTH CABLES
29		SEAT- BELT INSALLATION FOR THIRD PASSENGER ON BENCH SEAT	P68, P68B	SEP 76	INFORMATION ONLY	ON CUSTOMER OPTION
30	B	REPLACEMENT OF FUEL FILTER BOWL, PARTENAVIA P/N 68-7.1005 MANUFACTURED BY "SECONDO MONA" P/N's 7760 AND 7760-A	P68, P68B	JUN 77	MANDATORY ACTION	IMMEDIATELY ON RECEIPT OF THE KIT
31		CHECK FOR CORRECT ELECTRICAL CONNECTIONS TO THE BATTERY AND THE ALTERNATOR BREAKERS	P68B	JUN 77	MANDATORY ACTION	AT THE NEXT ENGINE RUN AFTER RECEIPT OF THIS S.B.
32	A	RUDDER TRIM CONTROL ROD P/N 68-5.6053-2	P68, P68B	AUG 77	MANDATORY ACTION	IMMEDIATELY
33	1	FLAP ACTUATOR SWITCH P/N NOR 7.345-1	P68B	OCT 77	MANDATORY ACTION	WITHIN THE NEXT 100 HOUR INSPECTION
34	1	FIN REINFORCEMENT/RUDDER UPPER HINGE ATTACHMENT AREA	P68, P68B	FEB 78	MANDATORY ACTION	AT THE NEXT 100 HOUR INSPECTION
35		VOLTAGE-REGULATOR	P68, P68B	MAR 78	RECOMMENDED ACTION	AS SOON AS POSSIBLE

Note (*): Periodical Inspection Bulletin

Service Bulletins

S.B. No.	Rev. No.	SUBJECT	VARIANT AFFECTED	Rev. DATE	TYPE	TIME OF COMPLIANCE
36	2	STABILATOR BALANCE WEIGHT ATTACHMENT CHANNEL	P68, P68B	MAR 78	MANDATORY ACTION	A/C < 500 F.H. AT 500 H. INSPECT. ; A/C > 500 F.H. AT NEXT 100 H. INSPECTION
37	2	JOINT END FOR PROPELLER PITCH CONTROL	P68, P68B	NOV 78	MANDATORY ACTION	WITHIN OCT. 31 st 1978
38	2	FUEL PUMP COOLING DEVICE	P68, P68B	DEC 78	RECOMMENDED ACTION	AT USER'S DISCRETION
39	1	INTERFERENCE BETWEEN ELECTRICAL CABLES AND ENGINE OIL TUBES	P68, P68B	NOV 78	RECOMMENDED ACTION	ON CUSTOMER OPTION
40	1	FRAME No. 3 AND RUDDER PEDAL INTERCONNECTING BELL CRANK BRACKETS	P68, P68B	MAR 80	MANDATORY ACTION	A/C < 500 H. AT 500 H. INSPECT. ; * A/C > 500 H. BEFORE NEXT FLIGHT
41		LONGITUDINAL TRIM SYSTEM	P68, P68B	OCT 78	MANDATORY ACTION	AT NEXT 100 HOUR INSPECT.
42	1	JOINTS-END FOR ENGINE MIXTURE AND THROTTLE CONTROLS	P68, P68B	MAY 79	INFORMATION ONLY	ON CUSTOMER OPTION
43		AUXILIARY FUEL PUMP DRAINAGE	P68, P68B	JUN 79	RECOMMENDED ACTION	ON CUSTOMER OPTION
44		ENGINE AIR INTAKE FILTER	P68, P68B	JUL 79	RECOMMENDED ACTION	ON CUSTOMER OPTION
45		OIL COOLER LEFT ELBOW FITTING	P68, P68B	JUL 79	MANDATORY ACTION	AS SPECIFIED IN BULLETIN
46		FLAP OPERATING SWITCH	P68, P68B	SEP 79	INFORMATION ONLY	ON CUSTOMER OPTION
47		STABILATOR TRIM TAB INDICATOR	P68B	OCT 79	RECOMMENDED ACTION	ON CUSTOMER OPTION
*48	1	CONTROL WHEEL ROD UNIVERSAL JOINT	P68, P68B, P68C, P68C-TC	DEC 94	MANDATORY ACTION	AS INDICATED IN BULLETIN
49		ALTERNATOR OUTPUT CABLE	P68, P68B, P68C	JUL 80	MANDATORY ACTION	AT OWNER'S EARLIEST CONVENIENCE
50		NOT ISSUED				
51		MAGNETO'S GROUND WIRE	P68, P68B, P68C	APR 81	MANDATORY ACTION	AT NEXT INSPECTION
52		FUEL SELECTOR CONTROL SYSTEM	P68B, P68C, P68C-TC,	MAR 81	RECOMMENDED ACTION	AT NEXT INSPECTION
53		ENGINE AIR ALTERNATE TUBE	P68, P68B, P68C, P68 Observer	OCT 81	INFORMATION ONLY	ON CUSTOMER OPTION

Note (*): Periodical Inspection Bulletin

ISSUED

01 March 2010

Page 3 of 18

Service Bulletins

S.B. No.	Rev. No.	SUBJECT	VARIANT AFFECTED	Rev. DATE	TYPE	TIME OF COMPLIANCE
54		FUEL PIPES – LENGTHS BEHIND ENGINE COMPARTMENT FIREWALL	P68C-TC	JUL 82	MANDATORY ACTION	BEFORE NEXT FLIGHT
55	1	FLAP ACTUATOR SWITCH	P68B, P68C, P68C-TC	SEP 82	MANDATORY ACTION	AT THE NEXT 500 HOUR INSPECTION
56		FLAP BELLCRANK ATTACHMENT MOUNTING BRACKETS	P68, P68B, P68C, P68C-TC, P68 Observer	OCT 82	MANDATORY ACTION	AS INDICATED IN BULLETIN
57		STABILATOR TORQUE TUBE BRACKET ATTACHMENT BOLTS	P68, P68B, P68C, P68C-TC, P68 Observer	MAR 83	MANDATORY ACTION	IMMEDIATELY
58		REINFORCEMENT RING TURBOCHARGER INLET AIR TUBE	P68C-TC	JUN 83	INFORMATION ONLY	ON CUSTOMER OPTION
59	2	AILERON CONTROL	P68C-TC	JUN 84	MANDATORY ACTION	AT NEXT 100 HOUR INSPECTION
60		LYCOMING SERVICE BULLETIN No. 466	SEE LYC. S.B.	FEB 94	RECOMMENDED ACTION	SEE LYC. S.B.
61	3	FUEL AND JANITROL LINES	P68, P68B, P68R, P68C, P68C-TC, P68 Observer P68TC Observer,	NOV 95	MANDATORY ACTION	IN THE NEXT 50 FLIGHT H. OR 30 DAYS FROM S.B. RECEPTION
62		RUDDER UPPER HINGE BRACKET	P68, P68B, P68C, P68C-TC, P68 Observer	JUN 84	INFORMATION ONLY	ON CUSTOMER OPTION
63	1	STABILATOR CONTROL STOP	P68, P68B, P68C, P68C-TC, P68 Observer P68TC Observer	JUN 84	MANDATORY ACTION	TO THE NEXT 100 HOUR INSPECTION
64	1	AILERON CONTROL CHAIN	P68, P68B, P68C, P68C-TC, P68 Observer, P68TC Observer	SEP 84	MANDATORY ACTION	IMMEDIATELY
65	3	SPAR CAP CRACKS	P68, P68B, P68C, P68C-TC, P68 Observer, P68TC Observer	SEP 85	MANDATORY ACTION	SEE S.B.
66		OIL COOLER AIR INTAKE BAFFLE	P68C-TC	SEP 84	RECOMMENDED ACTION	ON CUSTOMER OPTION
*67	1	FIBRE GLASS LEADING EDGE	P68, P68B, P68C, P68C-TC	NOV 86	MANDATORY ACTION	EVERY 100 FLIGHT HOUR
68		INTERFERENCE BETWEEN BRAKE OIL TUBE AND RIGHT HAND AILERON CABLE	P68, P68B, P68C, P68C-TC, P68 Observer, P68TC Observer	JAN 86	MANDATORY ACTION	WITHIN NEXT 10 FLIGHT HOUR FROM RECEIPT OF THIS S.B.
69		NOSE LANDING GEAR ASSY: CONNECTION BETWEEN GEAR PISTON P/N 68-4.6013-1 AND INNER CYLINDER P/N 68-4.6005-1	P68, P68B	JUL 86	RECOMMENDED ACTION	SUGGESTED AT NEXT 500 HR INSPECTION

Note (*): Periodical Inspection Bulletin

ISSUED

01 March 2010

Page 4 of 18

Service Bulletins

S.B. No.	Rev. No.	SUBJECT	VARIANT AFFECTED	Rev. DATE	TYPE	TIME OF COMPLIANCE	
*70	2	ENGINE MOUNT/WING ATTACHMENT BRACKET P/N's 68-1.2025(B)-1/-2 68-1.2027-1	P68, P68B, P68C, P68C-TC, P68 Observer, P68TC Observer	JAN 89	MANDATORY ACTION	SECT.1: AT 5 YEARS S.N. SECT. 3: EVERY 500 HR OR 2 YEARS FROM SECT. 1	
71		AVCO LYCOMING SERVICE BULLETIN No. 473	P68C-TC, P68TC Observer	SEP 86	MANDATORY ACTION	REFER TO LYCOMING S.B.	
*72		RUDDER CONTROL CABLES	P68 Variants	FEB 88	RECOMMENDED ACTION	3500 HOUR	
73	1	STABILATOR TRIM TABS	P68, P68B, P68C, P68C-TC, P68 Observer, P68TC Observer	JUL 88	MANDATORY ACTION	WITHIN NEXT SCHEDULED INSPECTION OF 100 HOUR	
*74		ELECTRICAL SYSTEM	P68, P68B, P68C, P68C-TC, P68 Observer, P68TC Observer	NOV 88	RECOMMENDED ACTION	EVERY 500 HR OR AT LEAST EVERY 2 YEARS	
*75	3	FLIGHT CONTROL CABLES	P68 Variants	MAY 96	MANDATORY ACTION	EVERY 100, 200, 400, 1000 FLIGHT HOUR AS INDICATED IN S.B.	
76	1	ENGINE MOUNT INSTALLATION	P68, P68B, P68C, P68C-TC, P68 Observer; P68TC Observer	JAN 89	MANDATORY ACTION	AS INDICATED IN S.B.	
77	1	CARGO VERSION	P68B, P68C, P68C-TC, P68 Observer; P68TC Observer	APR 04	INFORMATION ONLY	ON CUSTOMER OPTION	
78		AUXILIARY WING FUEL TANKS SYSTEM	INACTIVE Refer to Service Letter No. 15				
79		INCREASE OF THE MAX TAKE-OFF WEIGHT	P68B, P68C, P68 Observer	MAR 91	INFORMATION ONLY	ON CUSTOMER OPTION	
80		LARGER NOSE WHEEL INSTALLATION	P68C, P68 Observer	MAR 91	INFORMATION ONLY	ON CUSTOMER OPTION	
*81	1	ENGINE AND PROPELLER CONTROL CABLES	P68, P68B, P68C, P68C-TC, P68 Observer, P68TC Observer, P68 Observer 2	NOV 94	MANDATORY ACTION	WITHIN 25 F.H. AND EVERY 25 F.H. REPLACEMENT WITHIN 12 MONTHS	
82		ENGINE MOUNT – LEFT AND RIGHT	P68C-TC, P68TC Observer	JAN 91	MANDATORY ACTION	IN THE NEXT 25 F.H. OR 30 DAYS FROM S.B. RECEPTION	
*83		MUFFLER ASSEMBLY LH AND RH P/N 6.1033-3/-4	P68, P68B, P68C, P68 Observer, P68 Observer 2	FEB 91	MANDATORY ACTION	AT THE NEXT 100 HR INSPECTION AND EVERY 200 HR	

Note (*): Periodical Inspection Bulletin

ISSUED

01 March 2010

Page 5 of 18

Service Bulletins

S.B. No.	Rev. No.	SUBJECT	VARIANT AFFECTED	Rev. DATE	TYPE	TIME OF COMPLIANCE
84		FRAME No. 1	P68C, P68C-TC	MAR 91	MANDATORY ACTION	AT THE NEXT 100 HR INSPECTION
85		HORIZONTAL TAIL PLANE	P68, P68B, P68C, P68C-TC, P68 Observer	JUL 91	MANDATORY ACTION	PART A ON RECEIPT OF S.B. PART B WITHIN DEC. 31, 1991
86		FUEL AND ENGINE OIL INSTRUMENTS SYSTEM	P68B, P68C, P68C-TC, P68 Observer P68TC Observer P68 Observer 2	FEB 92	RECOMMENDED ACTION	ON CUSTOMER OPTION OR IN CASE OF LEAKAGE IN PROXI. OF THE AN894D4-2 REDUCTION
*87	1	STABILATOR TORQUE TUBE	P68 Variants	APR 92	MANDATORY ACTION	WITHIN 50 HRS FROM S.B. AND EVERY 200 F.H. AS SPECIFIED IN S.B.
*88		ENGINE OIL COOLER SYSTEM HOSES (NOR 7.405-1)	P68, P68B, P68R, P68C, P68 Observer, P68 Observer 2,	NOV 93	MANDATORY ACTION	WITHIN 25 HR FROM THIS S.B. RECEPTION AND EVERY ENG. OIL COOLER HOSE REPL.
89		"IFR" INSTRUMENT PANEL CONFIGURATION	P68 Observer, P68TC Observer, P68 Observer 2	NOV 93	MANDATORY ACTION	WITHIN 6 MONTHS OF THE APPROVAL DATE OF THIS S.B.
90		FUEL SELECTOR CONTROL	P68 Variants	NOV 93	MANDATORY ACTION	ON SERVICE BULLETIN RECEPTION
*91		STABIL.T.TUBE ATT.SHELVES (5.3017-1/2) FLAP HINGE SHELVES (1.3041-3/4; 1.3049-2) AIL. HINGE SHELVES (1.3045-2; 1.3047-1/2)	P68 Variants	NOV 93	MANDATORY ACTION	AT NEXT 100 HOUR INSPECTION
92		PENDING ISSUE				
*93		INSPECTION OF THE INTERNAL AREA OF THE WING BOX BETWEEN RIBS No. 6 AND 8 (ENGINE NACELLE AREA)	P68 Variants	NOV 95	MANDATORY ACTION	A) <500=500; - 500=NEXT 100H B) 300 OR 500 H (REP. INS.) C) 2000 H AFTER REPLAC.
94		PENDING ISSUE				
95	1	FLIGHT CONTROL LAYOUT MODIFICATION AS PER MOD.P68/03	P68 Variants	AUG 99	RECOMMENDED ACTION	ON CUSTOMER OPTION
96		PENDING ISSUE				

Note (*): Periodical Inspection Bulletin

ISSUED

Service Bulletins

S.B. No.	Rev. No.	SUBJECT	VARIANT AFFECTED	Rev. DATE	TYPE	TIME OF COMPLIANCE
97		PENDING ISSUE				
98		NOSE LANDING GEAR INSPECTION/REPLACEMENT	P68 Observer, P68 Observer 2, P68TC Observer	JUL 99	MANDATORY ACTION	WITHIN THE NEXT 200 F. H. OR WITHIN 12 MONTHS OF THE APPROVAL DATE OF THIS S.B, WICHEVER FIRST OCCURS
99	1	LH & RH BOLTS ATTACHING THE MAIN LANDING GEAR LEAF SPRING JOINTS TO THE FUSELAGE CENTRE BEAM	P68 Variants except P68R	MAR 00	MANDATORY ACTION	ON SERVICE BULLETIN RECEPTION
100		PENDING ISSUE				
101		PENDING ISSUE				
102		PENDING ISSUE				
103		PENDING ISSUE				
104		PENDING ISSUE				
105		PENDING ISSUE				
106		PENDING ISSUE				
107		INSTALLATION OF NEW DE-ICE BOOT AIR FILTER P/N NOR7.483-8 (RAPCO P/N RA1J4-7)	P68C, P68 Observer 2	FEB 09	INFORMATION ONLY	AT OWNER'S DISCRETION
108		STABILATOR TRIM CONTROL – FRAME 16 PULLEY ASSEMBLY	P68C, P68C-TC, P68 Observer 2, P68TC Observer	MAY 01	MANDATORY ACTION	Part A: BEFORE NEXT FLIGHT AT S.B. RECEPTION Part B: AT NEXT 200 HOUR INSPECTION
109		FUEL SELECTOR CONTROL	P68C, P68 Observer 2	DEC 01	MANDATORY ACTION	WITHIN THE NEXT 15 FLIGHT HOURS
110		FLIGHT CONTROLS – INSPECTION TO ENSURE ABSENCE OF INTERFERENCE BETWEEN CONTROL COLUMN INTERCONNECTION CHAIN/ENGINE CONTROL PEDESTAL, AND INSTALLATION OF DOWNWARD PITCH FULL-TRAVEL LIMIT ASSY, P/N 5.3077-1 / -2	P68 Observer, P68 Observer 2, P68TC Observer	MAR 02	MANDATORY ACTION	Part A: BEFORE NEXT FLIGHT AT S.B. RECEPTION Part B: WITHIN 30 DAYS AFTER S.B. RECEPTION
111	1	- AILERON CONTROL - STABILATOR CONTROL - RUDDER CONTROL - FLAP CONTROL	P68 Variants	FEB 02	MANDATORY ACTION	Part A: BEFORE NEXT FLIGHT AT S.B. RECEPTION Part B: WITHIN 15 DAYS OR AT THE NEXT 50 HOUR INSPECTION WHICHEVER OCCURS FIRST

Note (*): Periodical Inspection Bulletin

ISSUED

01 March 2010

Page 7 of 18

Service Bulletins

S.B. No.	Rev. No.	SUBJECT	VARIANT AFFECTED	Rev. DATE	TYPE	TIME OF COMPLIANCE
112		INSTALLATION OF PHOTOGRAMMETRIC HATCH	P68C, P68 Observer 2	SEP 03	INFORMATION ONLY	AT OWNER'S DISCRETION
*113		FUEL SYSTEM	P68 Variants	JUL 02	MANDATORY ACTION	WITHIN THE NEXT 50 HOURS INSPECTION AND HOWEVER NOT MORE THAN 3 MONTHS SINCE RECEIVING THE BULLETIN AND EVERY 100 HR INSPECTION
*114	2	TRANSMISSION OF TECHNICAL DOCUMENTATION ISSUED BY "PARKER HANNIFIN CORPORATION – AIRBORNE DIVISION". - VACUUM SYSTEM - PNEUMATIC DE-ICE SYSTEM	P68 Variants	JUL 06	MANDATORY ACTION	AS REQUIRED BY PARKER HANNIFIN CORPORATION – AIRBORNE DIVISION
115		INSTALLATION OF PASSENGER INERTIAL SAFETY BELTS P/N NOR7.229-1/-2	P68 Variants	MAR 03	INFORMATION ONLY	AT OWNER'S DISCRETION
116	2	INSTALLATION OF NEW FUEL SELECTOR VALVE P/N NV7.001-59C	P68B, P68C, P68 Observer, P68 Observer 2, P68C-TC, P68TC Observer	MAR 07	INFORMATION ONLY	AT OWNER'S DISCRETION
117		REDUCTION OF MAXIMUM TAKE-OFF WEIGHT FROM 2084 Kg TO 1990 Kg AND INCREMENT OF MAXIMUM TAKE-OFF WEIGHT FROM 1990 Kg TO 2084 Kg.	P68C	SEP 03	INFORMATION ONLY	AT OWNER'S DISCRETION
118		INSTALLATION OF NEW DOOR HINGES P/Nos. 2.6255-1/-2/-3/-4	P68 Variants	MAR 03	INFORMATION ONLY	AT OWNER'S DISCRETION
119		FUEL LEVEL PROBE P/N 7.1337-6	P68C, P68 Observer 2,	APR 03	RECOMMENDED ACTION	AT OWNER'S DISCRETION
*120	1	WING AND STABILATOR STRUCTURES – SAFE FATIGUE LIMITS	P68 Variants	JUN 06	MANDATORY ACTION	AS INDICATED IN PARA. 1.4 OF THIS SERVICE BULLETIN
121		PENDING ISSUE				
122		REDUCTION OF MAXIMUM TAKE-OFF WEIGHT FROM 2084 Kg TO 1990 Kg AND INCREMENT OF MAXIMUM TAKE-OFF WEIGHT FROM 1990 Kg TO 2084 Kg.	P68 Observer 2	SEP 03	INFORMATION ONLY	AT OWNER'S DISCRETION
123		PENDING ISSUE				
124		INSTALLATION OF NEW ENGINE AIR INTAKE FILTER P/N BA-162-E	P68B, P68R, P68C, P68 Observer, P68 Observer 2	OCT 04	INFORMATION ONLY	AT OWNER'S DISCRETION
125	1	INSTALLATION OF FUEL LEVEL INSPECTION CAPS	P68C, P68 Observer 2, P68TC Observer	JUL 04	INFORMATION ONLY	AT OWNER'S DISCRETION

Note (*): Periodical Inspection Bulletin

ISSUED

01 March 2010

Page 8 of 18

Service Bulletins

S.B. No.	Rev. No.	SUBJECT	VARIANT AFFECTED	Rev. DATE	TYPE	TIME OF COMPLIANCE
126	3	VACUUM SYSTEM – INSTALLATION OF THE NEW RELIEF VALVE P/N AA2H3-2 MANUFACTURED BY AERO ACCESSORIES INC. AND THE NEW AIR FILTER P/N RA1J7-1 MANUFACTURED BY RAPCO INC.	P68 Variants	JUL 09	INFORMATION ONLY	AT OWNER'S DISCRETION
127	1	INSTALLATION OF THE FUEL LEVEL SYSTEM MANUFACTURED BY FAREM AND COMPRISING ONE INDICATOR P/N NOR7.1037-3 AND TWO TRANSMITTERS P/N NOR7.289-1/-1A.	P68C, P68 Observer 2, P68TC Observer	SEP 04	INFORMATION ONLY	AT OWNER'S DISCRETION
128		EMERGENCY EVACUATION	P68C, P68 Observer 2, P68TC Observer	OCT 04	MANDATORY ACTION	WITHIN AND NO LATER THAN THE 30 TH OF DEC 2004
129		PENDING ISSUE				
130		RECONFIGURATION OF CABIN AIR HEATING SYSTEM	P68TC Observer S/N 415	SEP 04	INFORMATION ONLY	AT OWNER'S DISCRETION
131		PENDING ISSUE				
132		PENDING ISSUE				
133		PENDING ISSUE				
134	2	FUEL TANKS RECONFIGURATION FROM "STD RANGE" TO "LONG RANGE"	P68 Variants	FEB 10	INFORMATION ONLY	AT OWNER'S DISCRETION
135		NEW CABIN HEATING SYSTEM INSTALLATION	P68C, P68 Observer 2	APR 05	INFORMATION ONLY	AT OWNER'S DISCRETION
136		INCREMENT OF MAXIMUM TAKE-OFF WEIGHT FROM 1990 Kg TO 2084 Kg.	P68C-TC	APR 05	INFORMATION ONLY	AT OWNER'S DISCRETION
137	1	INSTALLATION OF NEW HOT AIR DISTRIBUTOR ON FORWARD FAN HEATER.	P68C, P68 Observer 2	MAY 05	INFORMATION ONLY	AT OWNER'S DISCRETION
138		REPOSITIONING OF COM 2 ANTENNA	P68 Observer 2 S/N 423	MAY 05	INFORMATION ONLY	AT OWNER'S DISCRETION
139		PENDING ISSUE				
140		INSTALLATION OF NEW IMPROVED FWD FAN HEATER FOR THE WINDSHIELD DEFROSTING AS PER MOD.P68/82 PLUS MDM 019/07 AND MDM 005/08	P68 Observer 2 S/N 423	MAR 09	INFORMATION ONLY	AT OWNER'S DISCRETION
141		RETROFIT OF THE "KEITH" AIR CONDITIONING SYSTEM	P68 Variants	NOV 06	INFORMATION ONLY	AT OWNER'S DISCRETION
142		INSTALLATION OF THE ARTEX MODEL ME406 EMERGENCY LOCATOR TRANSMITTER AS PER CHANGE No. MOD.P68/77	P68 Observer 2 S/N 423	MAR 09	INFORMATION ONLY	AT OWNER'S DISCRETION
143	1	INSTALLATION OF NEW WINDSHIELD	P68 Observer, P68 Observer 2, P68TC Observer	OCT 09	INFORMATION ONLY	AT OWNER'S DISCRETION
144		INSTALLATION OF A TRAVEL STOP AT THE FULL POSITION OF THE FUEL LEVEL TRANSMITTER FAREM P/N NOR7.289-1 (LH) AND P/N NOR7.289-1A (RH) (OLD DRWG 7.1011)	P68 Variants	OCT 06	INFORMATION ONLY	AT OWNER'S DISCRETION

Note (*): Periodical Inspection Bulletin

ISSUED

01 March 2010

Page 9 of 18

Service Bulletins

S.B. No.	Rev. No.	SUBJECT	VARIANT AFFECTED	Rev. DATE	TYPE	TIME OF COMPLIANCE
145		PENDING ISSUE				
146	1	AERIAL SURVEY CONFIGURATION - WESCAM MX-15 AIRBORNE IMAGING SYSTEM INSTALLATION	P68 Observer 2 S/N 384	JUN 09	INFORMATION ONLY	AT OWNER'S DISCRETION
147		PENDING ISSUE				
148		UPPER ATTACHMENT BOLT OF THE NOSE LANDING GEAR STRUT	P68C, P68 Observer 2, P68TC Observer	DEC 06	INFORMATION ONLY	WITHIN THE NEXT SCHEDULED INSPECTION
149		PENDING ISSUE				
150		PENDING ISSUE				
151		PENDING ISSUE				
152		PENDING ISSUE				
153		PENDING ISSUE				
154		PENDING ISSUE				
155		INCREASE OF THE MAXIMUM ZERO FUEL WEIGHT FROM 1890 Kg TO 1967 Kg.	P68C FROM S/N 402 UP TO S/N 440	SEP 09	INFORMATION ONLY	AT OWNER'S DISCRETION
156		INSTALLATION OF 2 nd SENSITIVE ALTIMETER P/N NOR7.1003-1 (United Instruments P/N 5934PAD-1).	P68 Observer 2 S/N 441	APR 07	INFORMATION ONLY	AT OWNER'S DISCRETION
157		ENGINE STARTERS OPERATION	P68C, P68 Observer 2, P68TC Observer	MAY 07	INFORMATION ONLY	AT OWNER'S DISCRETION
158		- REPOSITIONING OF THE FIRE EXTINGUISHER P/N NOR7.227-5A. - REPLACEMENT OF THE PILOT AND COPILOT SEATS P/N 11KA2-0101VL WITH NEW SEATS P/N 11KA6-0101VL	P68 Observer 2 S/N 423	MAY 07	INFORMATION ONLY	AT OWNER'S DISCRETION
159		PENDING ISSUE				
160		INCREASE OF THE MAXIMUM TAKE-OFF WEIGHT FROM 1960 Kg TO 1990 Kg AND INCREASE OF THE MAXIMUM LANDING WEIGHT FROM 1860 Kg TO 1890 Kg.	P68, P68B	JUL 07	INFORMATION ONLY	AT OWNER'S DISCRETION
161		PENDING ISSUE				
162		WING SAFE LIFE LIMIT AND SPECIAL INSPECTIONS ON WING AND STABILATOR STRUCTURES	P68 Variants	MAR 10	MANDATORY ACTION	AS INDICATED IN PARA. 1.4 OF THIS SERVICE BULLETIN
163	3	MECHANICAL INTERFACE FOR THE INSTALLATION OF AN APPARATUS ON THE PHOTOGRAMMETRIC HATCH	P68 Observer S/N 329; P68C S/N 412; P68 Observer 2 S/N 422, P68B S/N 22; P68TC Observer S/Nos. 454; 456	JAN 10	INFORMATION ONLY	AT OWNER'S DISCRETION
164		PENDING ISSUE				
165		INSTALLATION OF NEW ENGINE AIR INTAKE FILTER P/N BA-161	P68C-TC; P68TC Observer	JUN 08	INFORMATION ONLY	AT OWNER'S DISCRETION

Note (*): Periodical Inspection Bulletin

ISSUED

01 March 2010

Page 10 of 18

Service Bulletins

S.B. No.	Rev. No.	SUBJECT	VARIANT AFFECTED	Rev. DATE	TYPE	TIME OF COMPLIANCE
166	1	INSTALLATION OF TWO SEAT TRAVEL STOPS FOR THE PASSENGER SEATS IN 2 ND ROW AND LEFT SEAT TRACKS MODIFICATION	P68C S/N 445; P68TC Observer S/N 442	MAY 08	MANDATORY ACTION	ON RECEIPT OF MODIFICATION KIT
167		PENDING ISSUE				
168		PENDING ISSUE				
169		PROVISION FOR "ICAROS" SCANNER SYSTEM INSTALLATION	P68 Observer 2 S/N 423	JUN 08	INFORMATION ONLY	AT OWNER'S DISCRETION
170		IMPROVEMENT OF THE CABIN VENTILATION SYSTEM	P68C S/N 443 AND 445	JUL 08	INFORMATION ONLY	AT OWNER'S DISCRETION
171		ENGINE MANIFOLD AIR PRESSURE SENSOR UNIT RELOCATION	P68C, P68 Observer 2, P68TC Observer	DEC 08	RECOMMENDED ACTION	AT OWNER'S DISCRETION
172		PENDING ISSUE				
173		PENDING ISSUE				
174		PENDING ISSUE				
175		PENDING ISSUE				
176		PENDING ISSUE				
177		IMPROVEMENT OF THE COCKPIT AIR CONDITIONING SYSTEM	P68 Observer 2 S/N 446, P68TC Observer S/Nos. 442, 444	FEB 09	INFORMATION ONLY	AT OWNER'S DISCRETION
178		PENDING ISSUE				
179		PENDING ISSUE				
180		INSTALLATION OF THE ARTEX MODEL ME406 EMERGENCY LOCATOR TRANSMITTER AS PER CHANGE No. MOD.P68/77.	P68 Variants	MAR 09	INFORMATION ONLY	AT OWNER'S DISCRETION
181		PENDING ISSUE				
182		PENDING ISSUE				
183	3	REPLACEMENT OF THE SAFETY BELTS P/N NOR7.229-1 (INERTIAL) AND P/N NOR7.229-2 (VENTRAL) WITH THE NEW SAFETY BELTS P/N NV7.001-9-A (AMSAFE P/N 3022-5-111-2396)	P68 S/Nos. 08; 11; 13; P68B S/N 147	JUL 09	INFORMATION ONLY	AT OWNER'S DISCRETION
184		IMPROVEMENT OF THE COCKPIT FRESH AIR SYSTEM	P68C S/Nos. 443, 445, 448	APR 09	INFORMATION ONLY	AT OWNER'S DISCRETION
185		IMPROVEMENT OF THE COCKPIT AIR CONDITIONING SYSTEM	P68C S/N 449	APR 09	INFORMATION ONLY	AT OWNER'S DISCRETION
186		15 Amp. Max. at 28 Vdc AUXILIARY POWER SOCKET INSTALLATION	P68 Observer 2 S/N 423	APR 09	INFORMATION ONLY	AT OWNER'S DISCRETION
187		REPLACEMENT OF THE 5A. BREAKER LABELED "AUTOMATIC CUT-OFF" WITH A NEW 10A. BREAKER.	P68 Variants from S/N 442 up to S/N 448	APR 09	INFORMATION ONLY	AT OWNER'S DISCRETION
188		28Vdc, 30 Amp. MAX AUXILIARY POWER SOCKET INSTALLATION	P68 Observer 2 S/N 384	JUN 09	INFORMATION ONLY	AT OWNER'S DISCRETION
189		IMPROVEMENT OF THE CABIN AIR CONDITIONING SYSTEM	P68 Observer 2 S/N 446	JUN 09	INFORMATION ONLY	AT OWNER'S DISCRETION

Note (*): Periodical Inspection Bulletin

ISSUED

01 March 2010

Page 11 of 18

Service Bulletins

S.B. No.	Rev. No.	SUBJECT	VARIANT AFFECTED	Rev. DATE	TYPE	TIME OF COMPLIANCE
190		PENDING ISSUE				
191		PENDING ISSUE				
192		INTERFERENCE BETWEEN THE NEW TO-360-C1A6D ENGINE CRANKCASE CASTING AND THE EXISTING FRONT RIGHT ENGINE BAFFLE AND THE PROPELLER DE-ICE BRUSH BLOCK	P68C-TC S/N 313	NOV 09	INFORMATION ONLY	AT ENGINE REPLACEMENT
193		PENDING ISSUE				
194		PENDING ISSUE				
195		PENDING ISSUE				
196		PENDING ISSUE				
197		PENDING ISSUE				
198		PENDING ISSUE				
199		FIRE EXTINGUISHER P/Nos NOR7.227-5A AND NOR7.227-5B MANUFACTURED BY FIRE FIGHTING ENTERPRISES LIMITED WITH P/Nos. BA51015-3 AND BA51015G-3 – IDENTIFICATION/REPLACEMENT	P68 Variants	JAN 10	MANDATORY ACTION	WITHIN 29 JANUARY 2010

Note (*): Periodical Inspection Bulletin

Service Instructions

S.I. No.	Rev. No.	SUBJECT	VARIANT AFFECTED	Rev. DATE		
01	1	NEW PARKING BRAKE DEVICE KIT P/N 68-004	P68B	NOV 78		
02	1	JOINT END FOR PROPELLER PITCH CONTROL – KIT P/N 68-005	P68, P68B	MAY 79		
03		MODIFICATION OF LONGITUDINAL TRIM SYSTEM KIT P/N 68-009	P68, P68B	OCT 78		
04		MODIFICATION OF LONGITUDINAL TRIM SYSTEM KIT P/N 68-010	P68, P68B	OCT 78		
05	1	JOINT ENDS FOR ENGINE MIXTURE AND THROTTLE CONTROLS	P68, P68B	MAY 79		
06	2	CONVERSION FOR PARACHUTE DOPPRING	P68B, P68C, P68C-TC, P68 Observer	APR 86		
07		FUEL SELECTOR VALVE CONTROL SYSTEM	P68, P68B	MAR 79		
08		STABILATOR TRIM INDICATOR MODIFICATON KIT P/N 68-014	P68B	OCT 79		
09	1	CONTROL WHEEL ROD UNIVERSAL JOINT	P68, P68B, P68R, P68C, P68C-TC	DEC 94		
10		ENGINE LOWER COWLING KIT P/N 68-017	P68B	APR 80		
11		RETROFITTING OF BAGGAGE DOOR INTERNAL OPENING MODIFICATION KIT P/N 68-019	P68B	JUL 80		
12		NOT APPLICABLE				
13		FUEL SELECTOR VALVE CONTROL KIT P/N 68-020	P68B, P68C, P68C-TC	MAR 81		
14	1	FUEL SYSTEM-AUXILIARY TANKS KIT P/N 68-026° e P/N 68-026B	P68B, P68C, P68C-TC	FEB 99		
15		OVERBOOST PRESSURE SWITCH KIT P/N 68-030	P68C-TC	SEP 83		
16		OIL COOLER AIR INTAKE BAFFLE KIT P/N 68-032	P68C-TC	SEP 84		
17		FUEL SYSTEM LINE KIT P/N 68-033	P68C-TC	JUN 84		
18		AILERON CONTROL KIT P/N 68-035	P68C-TC	JUN 84		
19	2	CONVERTING TO-360-C1A6D ENGINE TO THE NEW FUEL INJECTED TIO-360-C1A6D CONFIGURATION KIT P/N 68-039	P68C-TC	OCT 91		

ISSUED

01 March 2010

Page 13 of 18

Service Instructions

S.I. No.	Rev. No.	SUBJECT	VARIANT AFFECTED	Rev. DATE			
20		CABIN FLOOR	P68 Variants	JUL 85			
21		FIBERGLASS LEADING EDGE	P68, P68B, P68C, P68C-TC	AUG 85			
22		NOT APPLICABLE					
23	4	FUEL FERRY TANKS SYSTEM	P68C, P68C-TC, P68TC Observer, P68 Observer 2	JUN 00			
24		NOT APPLICABLE					
25		STARTER RELAY P/N NOR 369-5	P68 Variants	JAN 87			
26		WOODWARD MODEL 210655 PROP GOVERNOR	P68 Variants	FEB 87			
27		RADIO FILTER P/N NOR 7.385-12	INACTIVE Refer to Service Letter No. 15				
28		NOT APPLICABLE					
29		PASSENGERS LIGHT P/N NOR 7.335-10	P68 Variants	MAY 87			
30		NOT APPLICABLE					
31		TRIM-TAB STABILATOR ASSY	P68 Variants	JUL 88			
32		NOT APPLICABLE					
33		FLIGHT CONTROL CABLES Specification MIL-W-83420	P68 Variants	DEC 88			
34		NOT APPLICABLE					
35		TACHOMETER REPLACEMENT	P68C, P68C-TC	APR 89			
36		INSPECTION HOLES FOR AILERON CONTROL CABLES	P68 Observer, P68TC Observer	JUN 89			
37		ENGINE MOUNT BOLT INSPECTION	P68 Variants	JUN 89			
38		FUEL QUANTITY INDICATOR REPLACEMENT	P68B	JAN 90			
39		FUEL AND JANITROL SYSTEM LINES	P68C-TC, P68TC Observer	FEB 91			
40		FUEL AND JANITROL SYSTEM LINES	P68C, P68 Observer	FEB 91			
41		ERRATA CORRIGE AT PAGE B-38 OF THE MAINTENANCE MANUAL NOR 10.709-1B	P68C, P68C-TC, P68 Observer, P68TC Observer	FEB 91			
42		INCREASE OF MAXIMUM TAKEOFF WEIGHT	P68B, P68C, P68 Observer	FEB 90			

Service Instructions

S.I. No.	Rev. No.	SUBJECT	VARIANT AFFECTED	Rev. DATE		
43		LARGER NOSE WHEEL INSTALLATION	P68C	MAR 91		
44		LARGER NOSE WHEEL INSTALLATION	P68 Observer	MAR 91		
45		NOT APPLICABLE				
46		ENGINE OIL COOLER SYSTEM HOSES P/N NOR 7.404-1	INACTIVE Refer to Service Letter No. 15			
47		MODIFICATION RESULTING FROM ENGINE STARTER REPLACEMENT	P68, P68B, P68C, P68 Observer P68 Observer 2	MAY 91		
48		STABILATOR TORQUE TUBE	P68 Variants	FEB 92		
49		PROPELLER CONTROL CABLE	P68 Variants	FEB 92		
50		NOT APPLICABLE				
51	2	INSTALLATION OF NEW FLAP POSITION INDICATOR SYSTEM	P68 Variants	JUN 05		
52		NOT APPLICABLE				
53		PENDING ISSUE				
54		FUEL SELECTOR VALVE	P68, P68B	JUN 95		
55		PENDING ISSUE				
56	1	FLIGHT CONTROL LAYOUT MODIFICATION AS PER S.B. No 95	P68 Variants	AUG 99		
57		PENDING ISSUE				
58		PENDING ISSUE				
59		PENDING ISSUE				
60		PENDING ISSUE				
61	1	NEW EGT INDICATOR SYSTEM P/N NOR7.1035-1C (INDICATOR) P/N NOR7.323-18B (PROBE)	P68, P68B, P68R, P68C, P68 Observer, P68 Observer 2,	JUN 00		
62		PENDING ISSUE				
63		PENDING ISSUE				
64		INSTALLATION OF PHOTOGRAMMETRIC HATCH	P68C, P68 Observer 2	SEP 03		
65		PENDING ISSUE				
66		PENDING ISSUE				
67		PENDING ISSUE				
68		FUEL SELECTOR CONTROL	P68C, P68 Observer 2,	DEC 01		

ISSUED

01 March 2010

Page 15 of 18

Service Instructions

S.I. No.	Rev. No.	SUBJECT	VARIANT AFFECTED	Rev. DATE		
69	1	INSTALLATION OF NEW FUEL SELECTOR VALVE P/N NV7.001-59C	P68B, P68C, P68 Observer, P68 Observer 2, P68C-TC, P68TC Observer	MAR 04		
70		STABILATOR CONTROL SYSTEM	P68 Observer, P68TC Observer	MAR 02		
71		PENDING ISSUE				
72		PENDING ISSUE				
73	1	MAINTENANCE PROCEDURES FOR THE FUEL SELECTOR VALVE P/N NV7.001-59C	P68B, P68C, P68 Observer, P68 Observer 2, P68C-TC, P68TC Observer	MAR 04		
74	3	VACUUM SYSTEM – INSTALLATION OF THE NEW RELIEF VALVE P/N AA2H3-2 MANUFACTURED BY AERO ACCESSORIES INC. AND THE NEW AIR FILTER P/N RA1J7-1 MANUFACTURED BY RAPCO INC.	P68 Variants	JUL 09		
75		PENDING ISSUE				
76	1	INSTALLATION OF THE FUEL LEVEL SYSTEM MANUFACTURED BY FAREM AND COMPRISING ONE INDICATOR P/N NOR7.1037-3AND TWO TRANSMITTERS P/N NOR7.289-1/-1A	P68C, P68 Observer 2, P68TC Observer	SEP 04		
77	2	CALIBRATION PROCEDURE FOR THE FUEL LEVEL INDICATOR SYSTEM	P68 Variants	JUL 08		
78		PENDING ISSUE				
79		FUEL SYSTEM SERVICING	P68 Variants	SEP 04		
80		PENDING ISSUE				
81		NEW CABIN HEATING SYSTEM INSTALLATION	P68C, P68 Observer 2	APR 05		
82		INCREMENT OF MAXIMUM TAKE-OFF WEIGHT FROM 1990 Kg TO 2084 Kg.	P68C-TC	APR 05		
83		PENDING ISSUE				
84		RETROFIT OF THE "KEITH" AIR CONDITIONING SYSTEM	P68 Variants	NOV 06		
85		PENDING ISSUE				
86		PENDING ISSUE				
87		WING FRONT AND REAR SPARS REINFORCEMENTS - INSTALLATION OF THE KIT SB155	P68C FROM S/N 402 UP TO S/N 440,	SEP 09		

ISSUED

01 March 2010

Page 16 of 18

Service Instructions

S.I. No.	Rev. No.	SUBJECT	VARIANT AFFECTED	Rev. DATE		
88		TYPICAL REPAIR OF FRONT SPAR IN LEFT AND RIGHT WINGS	P68 Variants	MAR 10		
89		MODIFICATION ON FRONT AND REAR SPARS IN LEFT AND RIGHT WINGS FOR SAFE LIFE LIMIT EXTENSION	P68 Variants	MAR 10		
90		REMOVAL, INSTALLATION AND CALIBRATION PROCEDURE FOR THE AHRS AX1-200 UNIT	P68 Variants	JAN 10		

Service Letters

S.L. No.	Rev. No.	SUBJECT	VARIANT AFFECTED	Rev. DATE		
01		JANITROL B-4050 CABIN HEATING SYSTEM	P68 Variants	MAY 85		
02		P68 VARIANTS A/C MAINTENANCE SCHEDULE	P68 Variants	JUL 90		
03		ENGINE STARTER "PRESTOLITE MHB 4016"	P68, P68B, P68C, P68 Observer, P68 Observer 2	MAY 91		
04		NOT APPLICABLE				
05		NOT APPLICABLE				
06		NOT APPLICABLE				
07		NOT APPLICABLE				
08		PARTENAVIA COPYRIGHT AND TRADE MARK	P68 Variants	DEC 99		
09		MISALIGNED ENGINE NACELLE/COWL RIVET	P68 Variants	JAN 00	ALERT	
10		PENDING ISSUE				
11		RETROFIT OF OPTIONAL SYSTEMS CONTAINED IN THE AIRCRAFT ILLUSTRATED PARTS CATALOGUE	P68 Variants	APR 03		
12		SERVICE BULLETINS, SERVICE INSTRUCTIONS AND SERVICE LETTERS ISSUED BY PARTENAVIA	P68 Variants	FEB 04		
13		EMERGENCY EVACUATION	P68 Variants	JUL 04		
14		SPINNER SCREW TORQUE VALUE	P68 Variants	JUL 04		
15		SERVICE BULLETINS, SERVICE INSTRUCTIONS AND SERVICE LETTERS ISSUED BY PARTENAVIA	P68 Variants	FEB 06		
16		FIELD SERVICE REPORT	P68 Variants	FEB 06		
17		EASA – EMERGENCY AIRWORTHINESS DIRECTIVE AD No. 2009-0251-E "Fire Protection – Portable Fire Extinguishers – Identification /Replacement"	P68 Variants	NOV 09	ALERT	