



# *SF600 Variants*

*(Including SIAI MARCHETTI SF600 and SF600A Aircraft)*

***Index of Service Bulletins, Service Letters  
and Service Instructions  
Issued on 24 February 2010***

***NOR10.777-3***

### Service Bulletins

SB.No.	Rev.No.	SUBJECT	VARIANT AFFECTED	Rev.DATE	TYPE	TIME OF COMPLIANCE
SF600-01		RECONFIGURATION OF THE AIRCRAFT FROM P/N F1-00450-801 REV. T TO P/N F1-00400-803 REV. D.	SF600 S/N 06	APR 05	INFORMATION ONLY	AT CUSTOMER'S OPTION
SF600-02		RESERVED				
SF600-03		INSTALLATION OF GILL BATTERY P/N G-6381E	SF600A S/N 10	JAN 06	INFORMATION ONLY	AT CUSTOMER'S OPTION
SF600-04		UPDATE OF AIRCRAFT CONFIGURATION - INSTALLATION OF NARCO ELT 910 P/N 03754-0300 - INSTALLATION OF FIRE EXTINGUISHERS P/N NOR7.227-5B - UPDATE OF EXTERNAL DECALS	SF600A S/N 10	JAN 06	INFORMATION ONLY	AT CUSTOMER'S OPTION
SF600-05		RESERVED				
SF600-06		WING SAFE LIFE FATIGUE LIMIT	SF600 S/N 05 THROUGH S/N 09; SF600A S/N 10	JUN 08	INFORMATION ONLY	AT RECEIPT OF THE APPLICABLE CHANGE TO THE MAINTENANCE MANUAL
SF600-07	1	INSTALLATION OF THE ARTEX MODEL ME406 EMERGENCY LOCATOR TRANSMITTER AS PER CHANGE No. MOD.SF600/06.	SF600A S/N 10	FEB 10	INFORMATION ONLY	AT CUSTOMER'S OPTION
SF600-08		FIRE EXTINGUISHER P/Nos NOR7.227-5A AND NOR7.227-5B MANUFACTURED BY FIRE FIGHTING ENTERPRISES LIMITED WITH P/Nos. BA51015-3 AND BA51015G-3 – IDENTIFICATION/REPLACEMENT	SF600 SF600A	JAN 10	MANDATORY	Within 29 January 2010

### Service Instructions

SI.No.	Rev.No.	SUBJECT	VARIANT AFFECTED	Rev.DATE		
//	//	////////////////////////////////////	////////////////////////////////////	////////////////////////////////////		

### Service Letters

SL.No.	REV.No.	SUBJECT	VARIANT AFFECTED	REV.DATE		
SF600-01		TYPING ERROR IN CHAPTER 71-20-01, PAGE 201 OF THE AIRCRAFT MAINTENANCE MANUAL	SF600; SF600A	MAY 05		
SF600-02		FIELD SERVICE REPORT	SF600; SF600A	FEB 06		
SF600-03		EASA – EMERGENCY AIRWORTHINESS DIRECTIVE AD No. 2009-0251-E "Fire Protection – Portable Fire Extinguishers – Identification /Replacement"	SF600; SF600A	NOV 09		